NASAWATCH.COM

Requirements   Risk Management   Nonconformance   Reports   Information

Integrated Problem Reporting and Corrective Action (iPRACA)

WebPCASS

User ID
Data Last Updated:08-MAY-08

Search   Advanced Search   Reports   My WebPCASS   Help   iPRACA Intranet   iPRACA Ex

Version: 1.06.2

(Back) (Perform New Search)

Document Issue Part   Action Task   Full Detail   Full Tree   Alternate Trees

Document Data

Document Number: NC031890	Document Type: NC	Managed by Organization: 06 - Ground Operations	Document ID: 031890	Document Status: Active	Contract Number: SPOC
Program Code: SSP	Initiated Date: 2008-05-07	Closed Date:	Total Issues: 1	Total Issues Closed: 0	Legacy Number:

Related Documents:
No Related Documents Found

Document Attachments:
No Document Attachments Found

Issue Data

Issue Number: NC031890-01	Type: Minor		Status: Open	Software: N	Functional Criticality: 3	Hardware Criticality: 3
Recurring Issue: N	Certificate Environment Violated:		IFA Number:		Issue Closed Date:	

Issue Title: Tile inadvertently damaged by inelastic collision with terra firma following uncontrolled descent	Description: Tile inadvertently damaged by inelastic collision with terra firma following uncontrolled descent C-2 missing .5 inch Lx .5inch Wx .3inch D Note: A valiant effort to save the tile was made , the tech heroically juggled the tile to floor to no avail	Requirement:	08126 Reportable Indicator:	Alternate Number:

Assigned to Organization: 06 - Ground Operations	Assigned to Role/Group/Department: WC - Work Control / TAIROPF1 - OPF1 TAIR Station /	Individual:

Related Documents:
No Related Documents Found

Issue Attachments:
No Issue Attachments Found

Detected Information

Date Detected: 2008-05-07	Isolated Date:	Detected at Site: KSC	Detected at Building/Facility: OPF1	Work Center: MID	Supplier Location:
Detected by Organization: 06 - Ground Operations	Detected by Role/Group/Department: TECH - DSP - Dispositioner, Shop / TMID1 - OPF1 Tile Mid Shop / 0358520		Individual: Kuhn John E	
Detected During: DD014	WAD Type: TPSA		WAD Number: Lwng-4-30-158	
Detected by Supplier Number:	Name:		City:	State:

Issue Codes

Defect Code Category: DPD00-PHYSICAL DEFECT	Defect Code: DPD04-Nicked, Scratched, Chipped, Gouged, Galled, or	Cause Code Category:	Cause Code: -

NASAWATCH.COM

		Scored		

Apparent Cause Code Category: CP00-Process	Apparent Cause Code: CP02-Collateral Damage	Failure Mode Code: -	Prevailing Condition Code: -
Test Ops Code: -	Material Code: -	Recurrence Control: -	

Evaluation Data

FMEA/CIL Data

Section Number:	CIL Number:	CIL Date:	CIL Description:	FMEA/CIL Functional Criticality:	FMEA/CIL Hardware Criticality:	CIL Affected:	FMEA/CIL Comments:

Hazard Data

Organization:	HR Number:	HR Date:	Hazard Title:	HR Classification:	HR Affected:
Cause Number:	Cause Likelihood:	Severity:	Classification:	Hazard Comments:	

Risk Assessment Data

Risk Assessment Attachments:

No Risk Assessment Attachments Found

Engineering Assessment Data

Consequence of Observed FM:	Worst Case Consequence of Observed FM:	In-Flight Occurrence:	Vulnerability:	Failure Knowledge:	Work Around:	Impact Assessment Total Score:	Impact Assessment Date:

Issue Assessment Rollup Data

No Data Found

Part Data

Part/Program Number: V070-199716-103	Name: HRSI tile	Serial/Revision: 7DCOFK	Lot Number:	CAGE Code:
SMR:	Type:	Software: N	Part Installed: N	Hardware Software Class:
Hazardous:	Equivalent Part Group:	Part Criticality: 1	Detected End Item: OV	Number: 104
Flight: 030	STS: 125	Common Hardware:	Zone: 721L09	Element: V
System: 09	Sub-System: 19	Sub-Level Subsystem:	Quantity: 1	Unit of Measure: EA

Part Attachments:

No Part Attachments Found

Part Related Data

Related Part Type: NHA	Related Part Software: N	Related Part Installed: Y
Related Part/Program Number: V070-199716-097	Related Part/Program Name:	Related Part Serial Number:	Related Part Lot Number:
Related Part CAGE Code:	Related Part Common Hardware:	Related Part Common Hardware Element:

Curator: Data Warehouse

RDM: Donna Lee