

SCIENCE EXPERIMENTS. CREW OFF DUTY.

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:45	FE-1	DCS battery charging
07:45-07:55		PCMCIA card formatting
08:00-08:15	CDR	БМП Φ2 Absorption Cartridge regeneration (start)
08:25-08:30	FE-1	PCMCIA card formatting
09:30-09:35		Physical Exercise (RED)
09:35-10:35		
10:15-10:40	FE-2	TV (ISS-MCC) LDM PAO (To=10:16, T1, T2 ,T3 - from СПП)
10:35-10:40	FE-1	PCMCIA card formatting
10:40-12:10		Physical Exercise (TVIS)
11:05-11:25	CDR	Private Family Conference (<i>Ku + S-band</i>)
12:05-13:35		Physical Exercise (TVIS) day 2
12:05-13:35	FE-2	Physical Exercise (CEVIS)
12:10-12:15	FE-1	PCMCIA card formatting
12:15-12:20		DCS battery charging
12:35-12:40		PCMCIA card formatting
13:00-13:05		
13:30-13:35		
13:35-14:35	.	LUNCH
14:35-15:05	FE-2	COЖ maintenance.
14:35-14:45	FE-1	Terminate BSA battery charge
15:15-15:20		DCS battery charging
15:20-15:40	FE-2	Private Family Conference (<i>Ku + S-band</i>)
16:00-17:00		Physical Exercise (TVIS) day 4
17:00-18:00	CDR	Physical Exercise (TVIS) day 2
17:55-18:00	FE-1	DCS battery stowage
18:00-18:15	.	Daily Planning Conference (<i>S-band</i>)
18:15-18:35	FE-1	Evening work prep
18:30-19:30	CDR,FE-2	Evening work prep
18:35-18:50	FE-1	Private Family Conference (<i>Ku + S-band</i>)
18:50-19:30		Evening work prep
19:30-20:00	.	DINNER
20:00-20:20	CDR	Daily food prep
20:00-20:30	FE-1,FE-2	
20:20-20:35	CDR	БМП Φ2 Absorption Cartridge regeneration (termination)
20:30-21:30	FE-1,FE-2	Pre-sleep
20:35-21:30	CDR	
21:30-06:00	.	SLEEP
Task List	CDR	PLANTS-2. Payload status check

		PLANTS-2. Recharging water tank
		MATRYOSHKA-R. MOSFET-dosimeter reading

Note: See OSTP for references to US activities.
End of Radiogram